



Field Service Bulletin

FSB-0909-MISC-09
September 2, 2009

The serial numbers of the charger that need to be returned for exchange are:

- | | | |
|-----------|---------|-----------|
| PN3-56496 | through | PN3-57995 |
| PN3-61896 | through | PN3-62895 |
| PN3-68696 | through | PN3-69695 |
| PN3-72096 | through | PN3-72895 |
| PN3-73096 | through | PN3-73295 |
| PN3-69696 | through | PN3-70695 |
| PN3-80201 | through | PN3-81500 |
| PN3-57996 | through | PN3-59195 |
| PN3-62896 | through | PN3-64095 |
| PN3-67296 | through | PN3-68495 |
| PN3-70696 | through | PN3-71895 |
| PN3-74096 | through | PN3-74607 |
| PN3-74808 | through | PN3-75495 |
| PN3-59196 | through | PN3-61195 |
| PN3-64296 | through | PN3-65495 |
| PN3-65796 | through | PN3-66995 |
| PN3-73296 | through | PN3-74095 |
| PN3-75701 | through | PN3-76500 |

For Questions regarding this Service Bulletin, please contact EFJohnson at 1-800-328-3911 press 3



Field Service Bulletin

FSB-0909-MISC-09
September 2, 2009



The serial numbers of the charger kits that may have faulty cups are (return only the cups with serial numbers in the ranges above, the remainder of the kit are not affected):

- | | | |
|-----------|---------|-----------|
| PN3-61696 | through | PN3-61895 |
| PN3-64096 | through | PN3-64295 |
| PN3-68496 | through | PN3-68695 |
| PN3-71896 | through | PN3-72095 |
| PN3-74608 | through | PN3-74807 |
| PN3-61196 | through | PN3-61695 |
| PN3-65496 | through | PN3-65795 |
| PN3-66996 | through | PN3-67295 |
| PN3-72896 | through | PN3-73095 |
| PN3-75501 | through | PN3-75700 |

If you any charger cups within the serial number listings above, please contact Customer Service toll-free at 800-328-3911, option 5, or send an email to warranty@efjohnson.com for a replacement.

For Questions regarding this Service Bulletin, please contact EFJohnson at 1-800-328-3911 press 3