

Field Software Notice

To: **All 2600 Users**
Subject: **Software Release**

Platform: **2600**
Protocol: **Conventional**
Version Release #: **1.8.1**
Effective Release Date: **7/9/03**

Minimum Requirements:

PC Configure:	N/A	ARM:	N/A
PC Configure Code Upgrade Loader:	N/A	DSP:	N/A
PC Configure Boot Upgrade Loader:	N/A	PC Flash:	N/A
Radio Boot Code:	N/A	PC Tune:	N/A
Other:	N/A	PC Trunk:	N/A

Feature Additions:

1 - Added Transmit Enable functionality to Alarm 1 Input

Fixes:

- 1 - Improved audio quality when using Model 38 Repeater Panel.**
 - 2 - Improved repeater operation when Rx signal is over deviated.**
 - 3 - Corrected nuisance DSP Ack fault**
 - 4 - Corrected operation of Reflected Power Alarm.**
 - 5 - Added verification sequence to writing of RF Deck EEPROM**
 - 6 - Corrected write protect issue with RF Deck EEPROM**
 - 7 - Corrected DCS code inversion error occurring when operating without the use of a Model 38A repeater controller.**
 - 8 - Corrected operation when manual IP address input without leading zeros.**
 - 9 - Corrected operation when TX VCO is out of lock.**
 - 10 - Increased maximum allowed simultaneous VoIP virtual circuits from 4 to 10**
-

Part Numbers Affected:

2422631100CAAA, 2422631100CBAA, 2422631101CBAA, 2422631104BAAA, 2422631110BAAA,
2422631110CBAA, 2422631111CBAA, 2422631114BAAA, 2422631700CBAA, 2422631701CBAA,
2422634100CBAA, 2422634101CBAA, 2422644100CBAA, 2422644101CBAA

Continued on next page.

Notes:

If you would like a copy of this software, please contact Sue Baldini at 800-328-3911, extension 6970.

For Technical Questions regarding this Field Software Notice, please contact EFJohnson Technical Support at 800-328-3911, ext. 2.