



# *Field Service Bulletin*

FSB-0309-53X-07  
March 2, 2009

**Date:** March 2, 2009

**To:** All EFJohnson customers, dealers, and employees

**Subject:** Dodge Charger Engine Noise

We recently became aware of engine noise being heard while transmitting with a Series 4 5300 mobile radio that is installed in a Dodge Charger. We have resolved the issue by modifying a circuit in the control head. Please note that this issue is only with the Dodge Charger when using the Series 4 5300 dash mount or remote mount mobile radio.

If you experience this issue please contact Customer Service toll-free at 800-328-3911, option 3, or send an email to [customerservice@efjohnson.com](mailto:customerservice@efjohnson.com) to arrange for this enhancement.

For Questions regarding this Service Bulletin, please contact EFJohnson at 1-800-328-3911 press 3