

Field Service Bulletin

FSB-0411-MISC-02
April 29, 2011

Date: April 29, 2011
To: EFJohnson customers and dealers
Subject: Multi-bay charger power supply, 585-5100-350 (part of charger kits 250-5100-360 and 250-5100-365)


PRODUCT RECALL REVISED FOR PART NUMBER UPDATE ONLY

Original Product Recall dated April 8, 2011:

As an update to the Field Service Bulletin issued on August 25, 2010, we are now requesting that all of the power supplies referenced above be returned to EFJohnson for replacement due to a safety hazard identified with these units. For your reference, the replacement power supply unit has been assigned EFJohnson part number: 585-5100-351.

*** Update: The EFJohnson part number for the replacement power supply unit is now: 585-5100-350B.

Pictures of the recalled unit are provided below for additional clarification:



If you have one of these power supplies, please contact EFJohnson's warranty department for a replacement: call 800-328-3911, option 5 or email warranty@efjohnson.com.

For questions regarding this Service Bulletin, please contact EFJohnson at 1.800.328.3911 (option 3)

EFJohnson Technologies • 1440 Corporate Drive, Irving, TX 75038-2401
800.328.3911 • 972.819.0700 • Fax 972.819.0639

EFJohnson
TECHNOLOGIES
We Respond.

www.efjohnsontechologies.com