


Field Service Bulletin

To: Users of EFJohnson Clamshell Battery for the 5100 Portable Radio


Subject: Field Modification

EFJohnson has received complaints that the orange clamshell battery cover can be difficult to remove under some field conditions.

The solution to this issue is to remove the scallops on the inside of the orange covers. This can be a field modification using a file or grinding tool, or the covers can be returned to the EFJohnson factory where the scallops will be ground off. Removal of the scallops does not affect the fire certification of the clamshell battery or the radio.



Clamshell cover with "Scallops" removed.



If you would like to return a batch of the covers to the factory to have EFJohnson perform this work, we will pay shipping both directions and will turn them around within 24 hours (in small quantities). Please contact Sue at 800-328-3911, extension 6970 if you would like to utilize this option.

If you have any technical questions concerning the Field Service Bulletin, please call EFJohnson Technical Support at 800-328-3911, extension 2.