

Field Service Bulletin

To: Users of EFJohnson 4-bay battery charger bases

Subject: Fuses

EFJohnson has become aware that a few of the battery charger bases, shipped in the last quarter of 2003, may have the wrong value fuse. Four battery charger bases have been identified as having 2A fuses instead of the required 5A fuse.

This applies only to the 4-bay battery charger bases, part numbers 250-5100-240, 250-5100-245, 585-5100-240 and 585-5100-245.

EFJohnson is sending a quantity of 5A fuses to each purchaser of the battery charger bases listed above. Please verify the proper value of fuse is installed in the charger base, and replace with the 5A fuse as necessary.

Attached is a copy of the instruction sheet for replacing the fuse in the charger base.

If you have any technical questions concerning this Field Service Bulletin, please contact EFJohnson Technical Support at 800-328-3911, extension 2.

If you need additional fuses, please contact EFJohnson Warranty Administration at 800-328-3911, extension 6970.