

Field Service Bulletin

To: Users of 5300 Mobile Radios with Hand Held Controllers (HHC)

Subject: Hand Held Controller Hanger Screw Field Re-attachment

EF Johnson has discovered that the “hanger” on the back of the Hand Held Controller (585-5300-025), during normal use, may become loose or detach from the back of the HHC. The attached instruction describes the procedure for securing the screw that holds the “hanger” in place.

You may purchase Loctite® from your regular supply store, or from EFJohnson, part number 250-5100-009.

If you have questions, you may call 1-800-328-3911, and press the number 3 .