

Service Bulletin

To: All EFJohnson LTR Customers and EFJohnson Associates

Subject: Support Discontinuance for LTR Products

EFJohnson is committed to the continued support of customers and products, but key components for older LTR / Conventional products have become obsolete and supply can no longer be guaranteed. We therefore regret to announce that support for all LTR products and their accessories will be discontinued by EFJohnson, effective June 15, 2007.

EFJohnson will continue to meet all contractual commitments to support these products, but unless contracted otherwise, the following conditions will apply as of the effective date of this bulletin:

- ⇒ These products will not be accepted for repair at EFJohnson's Depot Repair facility.
- ⇒ Parts for these products will be available for purchase only until current supplies are exhausted.
- ⇒ Technical Support will no longer be available for these products.

This bulletin impacts all LTR subscriber and infrastructure products, including but not limited to, the following model numbers:

242-8170-xxx	800 MHz Portable
242-8171-xxx	800 MHz Portable
242-8172-xxx	800 MHz Portable
242-8173-xxx	800 MHz Portable
242-9883-2xx	800 MHz Mobile
242-9883-6xx	800 MHz Mobile
242-9888-2xx	800 MHz Mobile
242-9888-6xx	800 MHz Mobile

For Questions regarding this Service Bulletin, please contact EFJohnson at 1-800-328-3911 press 3

EFJohnson Corporate Headquarters 1440 Corporate Drive, Irving, TX 75038-2401 • 800.328.3911 • 972.819.0700 • fax 972.819.0639
8181 Professional Place, Suite 115, Landover, MD 20785 • 800.201.9755 • fax 301.306.1449
3900 NW 12th Street, Suite 200, Lincoln, NE 68521 • 402.474.4800 • fax 402. 479.8482
123 North State Street, Waseca, MN 56093-2918 • 507.837.5100 • fax 507.837.5120
3000 "A" Street, Suite 413-415, Anchorage, AK 99567
www.EFJohnson.com

Service Bulletin

242-2008-0xx	800 MHz Universal Station
242-2008-2xx	800 MHz LTR Repeater
242-2008-3xx	800 MHz LTR Repeater
242-2008-4xx	800 MHz LTR Repeater
242-2008-6xx	800 MHz LTR Repeater
242-2008-8xx	800 MHz LTR Repeater
242-9890-2xx	900 MHz Mobile
242-9890-6xx	900 MHz Mobile
242-9896-2xx	900 MHz Mobile
242-9896-6xx	900 MHz Mobile
242-2009-2xx	900 MHz LTR Repeater
242-2009-3xx	900 MHz LTR Repeater
242-2009-4xx	900 MHz LTR Repeater
242-2009-6xx	900 MHz LTR Repeater
242-9840-xxx	VHF / UHF Mobile
242-9843-2xx	VHF / UHF Mobile
242-9843-3xx	VHF / UHF Mobile
242-9843-6xx	VHF / UHF Mobile
242-9848-2xx	VHF / UHF Mobile
242-9848-6xx	VHF / UHF Mobile

For Questions regarding this Service Bulletin, please contact EFJohnson at 1-800-328-3911 press 3

EFJohnson Corporate Headquarters 1440 Corporate Drive, Irving, TX 75038-2401 • 800.328.3911 • 972.819.0700 • fax 972.819.0639

8181 Professional Place, Suite 115, Landover, MD 20785 • 800.201.9755 • fax 301.306.1449

3900 NW 12th Street, Suite 200, Lincoln, NE 68521 • 402.474.4800 • fax 402. 479.8482

123 North State Street, Waseca, MN 56093-2918 • 507.837.5100 • fax 507.837.5120

3000 "A" Street, Suite 413-415, Anchorage, AK 99567

www.EFJohnson.com