

Service Bulletin

To: Installers of EFJohnson Motorcycle Radios

Subject: 5300 Logic Board Modification Required to Use External Interface

EFJohnson is committed to the continued support of its customers and products. To that end, we are issuing this bulletin so that installers of EFJohnson Motorcycle Radios perform a minor modification for the radio to operate as desired. This modification is required when using the EFJohnson Motorcycle Kit (part number 250-5300-883), for IP25300 interfaces, and for any other application requiring power to be provided through the DB 25 Options connector. Failure to perform this modification will result in a fuse opening and no power being provided to the external device rendering the radio inoperable. Perform the modification required as shown in the following photographs.

For Questions regarding this Service Bulletin, please contact EFJohnson at 1-800-328-3911 press 3

EFJohnson Corporate Headquarters 1440 Corporate Drive, Irving, TX 75038-2401 • 800.328.3911 • 972.819.0700 • fax 972.819.0639

8181 Professional Place, Suite 115, Landover, MD 20785 • 800.201.9755 • fax 301.306.1449


3900 NW 12th Street, Suite 200, Lincoln, NE 68521 • 402.474.4800 • fax 402. 479.8482

123 North State Street, Waseca, MN 56093-2918 • 507.837.5100 • fax 507.837.5120

3000 "A" Street, Suite 413-415, Anchorage, AK 99567

www.EFJohnson.com

Service Bulletin




Rework Location

For Questions regarding this Service Bulletin, please contact EFJohnson at 1-800-328-3911 press 3

EFJohnson Corporate Headquarters 1440 Corporate Drive, Irving, TX 75038-2401 • 800.328.3911 • 972.819.0700 • fax 972.819.0639
8181 Professional Place, Suite 115, Landover, MD 20785 • 800.201.9755 • fax 301.306.1449
3900 NW 12th Street, Suite 200, Lincoln, NE 68521 • 402.474.4800 • fax 402. 479.8482
123 North State Street, Waseca, MN 56093-2918 • 507.837.5100 • fax 507.837.5120
3000 "A" Street, Suite 413-415, Anchorage, AK 99567
www.EFJohnson.com

Service Bulletin



Remove F1 fuse and replace with 1/4" length of 16 AWG bare wire, part number 597-0271-016

For Questions regarding this Service Bulletin, please contact EFJohnson at 1-800-328-3911 press 3

EFJohnson Corporate Headquarters 1440 Corporate Drive, Irving, TX 75038-2401 • 800.328.3911 • 972.819.0700 • fax 972.819.0639

8181 Professional Place, Suite 115, Landover, MD 20785 • 800.201.9755 • fax 301.306.1449

3900 NW 12th Street, Suite 200, Lincoln, NE 68521 • 402.474.4800 • fax 402. 479.8482

123 North State Street, Waseca, MN 56093-2918 • 507.837.5100 • fax 507.837.5120

3000 "A" Street, Suite 413-415, Anchorage, AK 99567

www.EFJohnson.com