

Field Software Notice

This Software Upgrade Notice has been coordinated and approved by Air Combat Command, Mr. Allen LaRoche, Personal Wireless Communications Systems Manager.

This upgrade is provided at no charge through your EF Johnson warranty. You will be contacted by an EF Johnson representative to arrange scheduling to meet your requirements.

If you have any questions, please feel free to contact Mr. Tom Holtman or Mr. Brad Chambers at our DOD Support Center (888) 262-5610.

To: ACC Users of EFJohnson 5100 Portable and 5300 Mobile Radios
Subject: Q2 2004 Software Release

Platform: 5100 Portables & 5300 Mobiles
Protocol: Conventional, SMARTNET/SmartZone/P25 Trunking

Minimum Requirements:

PC Configure: 1.24.0.0
PC Tune: 1.1.1.0

Feature Enhancements:

- **CORRECTED PARMS FAIL ERROR** - radio "parameter" process is re-designed to store the personality files in two locations within the radio, removing the possibility of a user PARMS failure.
 - **Added dynamic regrouping cancel** - define a button or add to menu the ability to disable or cancel a dynamic regroup order.
 - **Added P25 Trunking OTAR** - over-the-air encryption rekeying of a radio
 - **Add P25 Trunking Interconnect Functionality** - added telephone interconnect to P25 Trunking
 - **Low battery on start-up display** "Batt Low" rather than "DSP Fail" - when battery is so low the DSP can not run, the display will show "Batt Low" indicating the battery should be replaced
 - **DTMF key press tone duration** - Make key press tone last until DTMF key is released
 - **Password change option** -User must enter current password before a new password can be entered.
-